

**Re: Project 2009-03 Clair Avenue Pump Station and Sanitary Sewer
Infiltration and Inflow Study Including Subsurface Soil Investigations**

The Engineering Department in conjunction with the Department of Public Works are beginning the process of repairing and/or replacing the Clair Avenue pump station and sanitary sewer which is failing due extremely poor subsurface soil conditions. We believe that proper repairs to this system will dramatically reduce the amount inflow and infiltration of groundwater that we are currently experiencing.

Financing for this capital project is provided by a 2008 serial bond in the Public Works Capital Budget